

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8810250055 DOC. DATE: 88/10/11 NOTARIZED: NO DOCKET #  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269  
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270  
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287

AUTH. NAME AUTHOR AFFILIATION  
 HERDT, A. R. Region 3, Ofc of the Director  
 RECIP. NAME RECIPIENT AFFILIATION  
 TUCKER, H. B. Duke Power Co.

SUBJECT: Forwards Insp Repts 50-269/88-30, 50-270/88-30 & 50-287/88-30  
 on 880829-0902. No violations or deviations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 248  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES: AEOD/Ornstein: 1cy. 05000269  
 AEOD/Ornstein: 1cy. 05000270  
 AEOD/Ornstein: 1cy. 05000287

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-3 PD	1 1	PASTIS, H	1 1
INTERNAL:	ACRS	2 2	AEOD	1 1
	DEDRO	1 1	NRR MORISSEAU, D	1 1
	NRR/DLPQ/PEB 11	1 1	NRR/DLPQ/GAB 10	1 1
	NRR/DOEA DIR 11	1 1	NRR/DREP/EPB 10	1 1
	NRR/DREP/RPB 10	2 2	NRR/DRIS DIR 9A	1 1
	NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
	DE LIEBERMAN, J	1 1	OGC/HDS2	1 1
	<u>REG FILE</u> 02	1 1	RES/DSR DEPY	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		
NOTES:		1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

Yellow

OCT 11 1988

Docket Nos. 50-269, 50-270, 50-287  
License Nos. DPR-38, DPR-47, DPR-55

✓ Duke Power Company  
ATTN: Mr. H. B. Tucker, Vice President  
Nuclear Production Department  
422 South Church Street  
Charlotte, NC 28242

Gentlemen:

SUBJECT: INSPECTION REPORT NOS. 50-269/88-30, 50-270/88-30 AND 50-287/88-30

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by J. L. Coley on August 29 - September 2, 1988. The inspection included a review of activities authorized for your Oconee facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,



Alan R. Herdt, Chief  
Engineering Branch  
Division of Reactor Safety

Enclosure:  
NRC Inspection Report

cc w/encl: (See page 2)

1/1  
IE01

OCT 11 1988

Duke Power Company

2

cc w/encl:

M. S. Tuckman, Station Manager  
State of South Carolina

bcc w/encl:

NRC Resident Inspector  
DRS Technical Assistant

H. Pastis, NRR  
Document Control Desk

RII  
JLC  
JL Coley:tm  
09/19/88

RII  
Metasman  
09/5/88

RII  
Job Take  
09/5/88

RII  
TAPeebles  
09/6/88  
10