

*Central File*  
50-269  
270  
287

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

9 DEC 28 AM : 08  
December 19, 1979

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

TELEPHONE: AREA 704  
373-4083


Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: 50-269  
50-270  
50-287

Dear Mr. O'Reilly:

In response to your letter of November 2, 1979, which transmitted Nuclear Regulatory Commission IE-Bulletin 79-25, a review of Oconee Nuclear Station has been conducted. This review revealed that no Westinghouse BFD/NBFD relays are used or planned for use in safety related equipment at this station.

Very truly yours,



William O. Parker, Jr.

RLG:scs

cc: U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Discussion of Reactor Operation Inspection  
Washington, D. C. 20555

8002120092

*DYP*

490694  
ORIGINAL COPY

102