

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8907200238 DOC. DATE: 89/07/14 NOTARIZED: NO DOCKET #
 FACIL: 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 AUTH. NAME: TUCKER, H. B. AUTHOR AFFILIATION: Duke Power Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Document Control Branch (Document Control Desk)

SUBJECT: Informs that steam generator plugging & repair for current Unit 2 outage completed on 890614, per Tech Spec 4.17.6(a).

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: General Distribution

NOTES: ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	PD2-3 LA	1	1	PD2-3 PD	1	1
	WIENS, L	5	5			
INTERNAL:	ACRS	6	6	NRR/DEST/ADS 7E	1	1
	NRR/DEST/CEB 8H	1	1	NRR/DEST/ESB 8D	1	1
	NRR/DEST/ICSB	1	1	NRR/DEST/MTB 9H	1	1
	NRR/DEST/RSB 8E	1	1	NRR/DOEA/TSB 11	1	1
	NUDOCS-ABSTRACT	1	1	OC/LEMB	1	1
	OGC/HDS2	1	0	REG FILE		
	RES/DSIR/EIB	1	1			
EXTERNAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 28 ENCL 26

MA 4

RIDS/ADS

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

July 14, 1989


U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Oconee Nuclear Station, Unit 2
Docket Nos. 50-270
OTSG Tube Plugging and Repair

Gentlemen:

Pursuant to Oconee Nuclear Station Technical Specification 4.17.6(a), Duke Power Company is providing the following information concerning the Oconee Unit 2 steam generators. The steam generator plugging and repair for the current Unit 2 outage was completed on June 14, 1989. The "A" OTSG had a total of five (5) tubes removed from service by plugging. The "B" OTSG had a total of four (4) tubes removed from service by plugging.

Very truly yours,


Hal B. Tucker

PJN/27/td

cc: S. D. Ebner, Regional Administrator
U. S. Nuclear Regulatory Commission - Region II
101 Marietta Street, NW, Suite 2900
Atlanta, GA 30323

L. A. Wiens
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

P. H. Skinner
NRC Resident Inspector
Oconee Nuclear Station

8907200238 890714
PDR ADOCK 05000270
P PIC

A001
1/0