ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

AUTH.N. TUCKMAN	AME AUTHOR A ,M.S. Duke Powe NAME RECIPIEN	FFILIATION r Co. T AFFILIAT			DOCKET # 05000269
			s repaired re EOC-13	-	1
DISTRIBUTION CODE: A001D COPIES RECEIVED:LTR \underline{l} ENCL $\underline{\mathcal{O}}$ SIZE: \underline{l} TITLE: OR Submittal: General Distribution					
NOTES:					S
	RECIPIENT ID CODE/NAME PD2-3 LA WIENS,L	TITTE ENCL	RECIPIENT ID CODE/NAME PD2-3 PD	COPIES LTTR ENCL	A
INTERNAL:	ACRS NRR/DET/ESGB	6 6	NRR/DET/ECMB 7D NRR/DOEA/OTSB11	1 1	Γ
	NRR/DST 8E2	1 1	NRR/DST/SELB 7E NRR/DST/SRXB 8E	1 1	E
	NRR/DST/SICB8H7 NUDOCS-ABSTRACT OGC/HDS2 RES/DSIR/EIB	6 6 1 1 1 1 1 1 1 1 1 0	OC/LEMB REG FILE 01	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	S
EXTERNAL:	NRC PDR	1 1	NSIC	1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL

R Ι

D S

D

D

Duke Power Company Nuclear Production Dept. P.O. Box 1007 Charlotte, N.C. 28201-1007 M.S. TUCKMAN Vice President Nuclear Operations (704)373-3851



DUKE POWER

September 20, 1991

U. S. Nuclear Regulatory Commission ATT: Document Control Desk Washington, DC 10555

Subject:

Oconee Nuclear Station, Unit 1

Docket No. 50-269

Summary of Steam Generator Tubes Repaired

EOC-13 Outage

Pursuant to Technical Specification 4.17.6a, we wish to report that twelve(12) tubes were removed from service by plugging in the "B" Steam Generator. In addition, no tubes were sleeved in either Steam Generator. The repair of these tubes was completed on September 13, 1991.

Very truly yours,

M. S. Tuckman

M. S. Tuckman

LTB/

XC: S. D. Ebneter

Regional Admistrator, Region II

P. E. Harmon

Senior Resident Inspector

L. A. Wiens, ONRR

9109240351 910920 PDR ADOCK 05000269 P PDR 2001 1/0