

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9508210271 DOC.DATE: 95/08/09 NOTARIZED: NO DOCKET #
FACIL:50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269 P
AUTH.NAME AUTHOR AFFILIATION
HAMPTON, J.W. Duke Power Co. R
RECIP.NAME RECIPIENT AFFILIATION I
Document Control Branch (Document Control Desk) O

SUBJECT: Forwards Rev 1 to LER 269/95-05 re breach of TS due to
unlocked control rod patch panel.Rev corrects typo on cover
ltr of 950807.Cover ltr of 950807 inadvertently labeled as
voluntary LER. I

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+6 R
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc. I

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	PD2-2 PD	1 1	WIENS, L	1 1	T
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2	
	AEOD/SPD/RRAB	1 1	<u>FILE CENTER</u>	1 1	
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1	1
	NRR/DE/EMEB	1 1	NRR/DISP/PIPB	1 1	
	NRR/DRCH/HHFB	1 1	NRR/DRCH/HICB	1 1	
	NRR/DRCH/HOLB	1 1	NRR/DRPM/PECB	1 1	
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SPSB/B	1 1	D
	NRR/DSSA/SRXB	1 1	RES/DSIR/EIB	1 1	
	RGN2 FILE 01	1 1			O
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	2 2	
	NOAC MURPHY, G.A	1 1	NOAC POORE, W.	1 1	C
	NRC PDR	1 1	NUDOCS FULL TXT	1 1	

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
DESK, ROOM OWFN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM
DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 27 ENCL 27

A04



DUKE POWER

August 9, 1995

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
LER 269/95-05, Revision 1


Gentlemen:

We are submitting this LER revision to you to correct a typographical error on our cover letter. Our cover letter of August 7, 1995, was inadvertently labeled as a Voluntary LER.

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report (LER) 269/95-05, concerning a breach of technical specification due to an unlocked control rod patch panel.

This report is being submitted in accordance with 10 CFR 50.73 (a) (2) (i) (B). This event is considered to be of no significance with respect to the health and safety of the public.

Very truly yours,


J. W. Hampton
Vice President

/fts

Attachment

xc: Mr. S. D. Ebnetter
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, Georgia 30323

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Mr. L. A. Wiens
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. P. E. Harmon
NRC Resident Inspector
Oconee Nuclear Site

9508210271 950809
PDR ADDCK 05000269
S PDR

