

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9803240277      DOC. DATE: 98/03/14      NOTARIZED: NO      DOCKET #  
FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.      05000269  
AUTH. NAME:      AUTHOR AFFILIATION  
MCCOLLUM, W.R.      Duke Power Co.  
RECIP. NAME:      RECIPIENT AFFILIATION  
                                 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 98-004-00 re inoperability of ECCS & reactor bldg spray sys, due to borated water storage tank level indication calibr errors.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+1  
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 PD	1 1	LABARGE, D	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	1 1	<b>FILE CENTER</b>	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DET/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:  
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIST OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25



W. R. McCollum, Jr.  
Vice President

Duke Power  
Oconee Nuclear Site  
P.O. Box 1439  
Seneca, SC 29679  
(864) 885-3107 OFFICE  
(864) 885-3564 FAX

March 14, 1998

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287  
Licensee Event Report 269/98-04, Revision 00  
Problem Investigation Process No.: 0-098-0707

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is a preliminary Licensee Event Report 269/98-04, regarding inoperability of the Emergency Core Cooling System and Reactor Building Spray System due to Borated Water Storage Tank level indication calibration errors. The report is preliminary because additional time is needed to sufficiently evaluate the impact of a later, related occurrence on this event. The related occurrence will be reported as LER 269/98-06 and will be submitted on or before March 23, 1998. A supplement to this LER will be submitted at that time.

This report is being submitted in accordance with 10 CFR 50.73 (a) (2) (i) (B), (a) (2) (ii) (B), and (a) (2) (v) (D). This event did not adversely impact the health and safety of the public.

Very truly yours,

  
W. R. McCollum, Jr.

11  
Tezz



Attachment

9803240277 980314  
PDR ADOCK 05000269  
S PDR

Document Control Desk

Date: March 14, 1998

Page 2

cc: Mr. Luis A. Reyes  
Administrator, Region II  
U.S. Nuclear Regulatory Commission  
61 Forsyth Street, S. W., Suite 23T85  
Atlanta, GA 30303

Mr. D. E. LaBarge  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Reactor Regulation  
Washington, D.C. 20555

INPO Records Center  
700 Galleria Parkway, NW  
Atlanta, GA 30339-5957

Mr. M. A. Scott  
NRC Resident Inspector  
Oconee Nuclear Station

Date: March 14, 1998

Page 3

bxc: C.M. Misenheimer/EC08I

B.L. Walsh/EC11C

C.A. Patton/PB02L

P.H. Cox/NSRB/EC05N

R.G. Hull/EC07A

ELL/EC050

P.M. Abraham\*

W.W. Foster\*

J.C. Mumford\*

C.C. Jennings\*

R.L. Dobson\*

T.A. Ledford\*

T.J. Pettit\*

M.S. Kitlan\*

J.E. Snyder\*

G.B. Swindlehurst\*

B.K. Jones\*

T.E. Ryan\*

R.L. Bain\*

J.E. Burchfield\*

T.A. Saville\*

S.L. Nader\*

J.M. Davis\*

L.J. Azzarello\*

R.L. Barnes\*

D.V. Deatherage\*

M.K. Nazar\*

\*LOTUS NOTES Distribution