





Duke Energy Corporation

Oconee Nuclear Station  
P.O. Box 1439  
Seneca, SC 29679  
(864) 885-3107 OFFICE  
(864) 885-3564 FAX

W. R. McCollum, Jr.  
Vice President

September 14, 1998

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555


Subject: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287  
Licensee Event Report 269/97-02, Revision 02  
Problem Investigation Process No.: 2-097-0240 and  
0-098-3629

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report, 269/97-02, concerning "Reactor Building Cooling Units Technically Inoperable Due To Design Deficiency".

This is a supplemental report to include information related to additional analysis required by corrective actions in revision 01. It is being submitted in accordance with 10 CFR 50.73 (a) (2) (V) (D). This event is considered to be of no significance with respect to the health and safety of the public.

Very truly yours,


 for WRM

W. R. McCollum, Jr.

Attachment

9809180200 980914  
PDR ADDCK 05000269  
S PDR

40000



Document Control Desk

September 14, 1998

Page 2

xc:

Mr. Luis A. Reyes  
Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta St., NW, Suite 2900  
Atlanta, GA 30323

Mr. D. E. LaBarge  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Reactor Regulation  
Washington, D.C. 20555

INPO Records Center  
700 Galleria Parkway  
Atlanta, GA 30339-5957

Mr. M. A. Scott  
NRC Resident Inspector  
Oconee Nuclear Station