

94-31

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR: 9501090270      DOC. DATE: 95/01/03      NOTARIZED: NO      DOCKET #  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.      05000269  
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co.      05000270  
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co.      05000287

AUTH. NAME      AUTHOR AFFILIATION  
 HAMPTON, J.W.      Duke Power Co.  
 RECIP. NAME      RECIPIENT AFFILIATION  
                          Document Control Branch (Document Control Desk)

SUBJECT: Provides util justification for delay of NRC commitment item re completion of required testing to fully meet IST requirements.

DISTRIBUTION CODE: IE01D      COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 3  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-3 PD	1 1	WIENS, L	1 1
INTERNAL:	ACRS	2 2	AEOD/DEIB	1 1
	AEOD/SPD/RAB	1 1	AEOD/SPD/RRAB	1 1
	AEOD/TTC	1 1	DEDRO	1 1
	FILE CENTER 02	1 1	NRR/DORS/OEAB	1 1
	NRR/DRCH/HHFB	1 1	NRR/PMAS/IRCB-E	1 1
	NUDOCS-ABSTRACT	1 1	OE DIR	1 1
	OGC/HDS2	1 1	RGN2 FILE 01	1 1
EXTERNAL:	LITCO BRYCE, J H	1 1	NOAC	1 1
	NRC PDR	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 20 0

F  
F  
I  
C  
F  
I  
I  
Y  
1  
E  
C  
C  
U  
M  
E  
N  
T

Duke Power Company  
Oconee Nuclear Generation Department  
P.O. Box 1439  
Seneca, SC 29679

J.W. HAMPTON  
Vice President  
(803)885-3499 Office  
(704)373-5222 FAX



**DUKE POWER**

January 03, 1995

U.S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

Subject: Oconee Nuclear Site  
Docket Nos. 50-269, -270, -287  
Inspection Report 50-269, -270, -287/94-31  
Delay of NRC Commitment Item

Dear Sir:

By letter dated December 19, 1994 the NRC issued a Inspection Report No. 50-269/94-31, 50-270/94-31, and 50-287/94-31. On page 21 of the "Report Details", item 6.b., it is stated that "Plans and preparations were being made to accomplish the testing before the end of the year" regarding the testing of ASW check valve LPSW-502. (This valve is the Auxiliary Service Water Supply check valve to the High Pressure Injection Pump (HPIP) Motor coolers and is currently not tested within Duke's IST program.) The stated corrective action constitutes a commitment to the NRC. Duke has initiated this corrective action and determined that the complexity of this procedure development warrents a delay in the completion date.

The justification for delay in the completion date is that the required testing to fully meet IST requirements must be done in a Refueling Outage. Through thorough procedure review and system testing review by Oconee Engineering, it was concluded that Unit Cold Shutdown conditions are necessary since isolation of support systems to the HPIP motor coolers is required in order to perform an adequate flow test through LPSW-502.

Therefore, Duke requests to delay completion of this commitment until 16 June 1995 (Unit 3 EOC 15 Refueling Outage), with testing on Units 1 and 2 to follow in their next refueling outages during EOC 16 (02 Nov 1995) and EOC 15 (27 Mar 1996) respectively. This will still allow Duke to complete the procedure changes and perform the required testing commensurate with available resources in order to meet the full intent of the NRC commitment. This commitment delay will not reduce the level of health and safety to the public.

9501090270 950103  
PDR ADOCK 05000269  
PDR


Printed on recycled paper

JED 1/0

A phone conversation was held with Larry Mellen of NRC Region II on 29 December 1994 to inform him that Duke would be unable to meet the specified commitment date and that a letter requesting extension of this commitment date would be submitted by Duke to the NRC.

If there are any further questions about this item, please contact David Nix at (803) 885-3634.

Very truly yours,

  
J. W. Hampton

Document Control Desk  
January 03, 1995  
Page 2

cc: Mr. S. D. Ebnetter, Regional Administrator  
U. S. Nuclear Regulatory Commission, Region II

Mr. L. A. Wiens, Project Manager  
Office of Nuclear Reactor Regulation

Mr. P. E. Harmon  
Senior Resident Inspector  
Oconee Nuclear Site