

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Photon Measurements Plus, Indianapolis, Indiana 46260 Location Inspected: St. Vincent Hospital 2001 West 86th Street Indianapolis, Indiana</p> <p>REPORT NUMBER(S) 2016-001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>
--	--

<p>3. DOCKET NUMBER(S)</p> <p>030-36648</p>	<p>4. LICENSE NUMBER(S)</p> <p>13-32533-01</p>	<p>5. DATE(S) OF INSPECTION</p> <p>May 24, 2016</p>
---	--	---

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Geoffrey M. Warren		6/2/16
BRANCH CHIEF	Aaron T. McCraw		6/3/16

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Photon Measurements Plus, Indianapolis, Indiana 46260 Location Inspected: St. Vincent Hospital 2001 West 86th Street Indianapolis, Indiana</p> <p>REPORT NUMBER(S) 2016-001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>
---	---

<p>3. DOCKET NUMBER(S)</p> <p>030-36648</p>	<p>4. LICENSE NUMBER(S)</p> <p>13-32533-01</p>	<p>5. DATE(S) OF INSPECTION</p> <p>May 24, 2016</p>
---	--	---

<p>6. INSPECTION PROCEDURES USED</p> <p>87126</p>	<p>7. INSPECTION FOCUS AREAS</p> <p>03.01 - 03.07</p>
---	---

SUPPLEMENTAL INSPECTION INFORMATION

<p>1. PROGRAM CODE(S)</p> <p>03221</p>	<p>2. PRIORITY</p> <p>5</p>	<p>3. LICENSEE CONTACT</p> <p>Edward E. Wroblewski, M.A., RSO</p>	<p>4. TELEPHONE NUMBER</p> <p>(317) 755-9688</p>
--	-----------------------------	---	--

Main Office Inspection Next Inspection Date: May 2021

Field Office Inspection St Vincent Hosp, 2001 W. 86th St, Indianapolis

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine, unannounced, inspection. At this facility, the licensee calibrated survey instruments for clients using the cesium-137 calibration source owned and possessed by St. Vincent Hospital. Two licensee personnel calibrated two or three survey instruments monthly under this license; one individual worked only under supervision at the time of the inspection. Both individuals also worked for St. Vincent Hospital, but performed activities under the Photon Measurements Plus license outside their normal working hours for St. Vincent.

Performance Observations: No licensed activities were being performed at the time of the inspection. Licensee staff demonstrated survey meter calibration. The inspector noted no concerns with this activity. The inspector reviewed survey meter calibration documentation. Interviews with licensee personnel indicated adequate knowledge of radiation safety concepts and procedures. Dosimetry records indicated no exposures of regulatory concern. The inspector performed independent and confirmatory radiation measurements which indicated results consistent with licensee survey records and postings.

No violations were identified during this inspection.

The licensee's radiation safety officer was only available by telephone at the time of the inspection, so no inspection could be performed of leak testing and other activities at the authorized facility in Westfield, Indiana. The next inspector should focus on inspecting activities at the Westfield facility.

Warren, Geoffrey

From: Warren, Geoffrey
Sent: Friday, June 03, 2016 9:00 AM
To: 'edspmp.edward@gmail.com'
Subject: NRC Inspection Report - Photon Measurement Plus
Attachments: PMP 5-16 - NRC 591M.pdf

Enclosed is the inspection report we discussed, for the inspection I performed on May 24 of Photon Measurement Plus activities at St. Vincent Hospital.

Please contact me if you have any questions.

--

Geoffrey Warren
Senior Health Physicist
NRC Region III
630-829-9742