

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 790.1230262 DOC. DATE: 79/01/15 NOTARIZED: NO

DOCKET #
05000269

FACIL: 50-269 OCONEE #1, DUKE POWER CO.

AUTH. NAME: WILSON, K.R.
AUTHOR AFFILIATION: DUKE POWER CO.
RECIP. NAME: WILSON, K.R.
RECIPIENT AFFILIATION: DUKE POWER CO.

**REG. 2, ATLANTA, OFF. OF THE DIRECTOR

SUBJECT: LER 78-027/03L-0 on 781214: Tave statalarm began to act erratically. Power cord supplying Tave recorder shorted causing apparent (not real) drop in Tave of 13 degrees F. Cause of Tave cord short not identified.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3+3
TITLE: INCIDENT REPORTS

NOTES: M. CUNNINGHAM - ALL AMENDS TO FSAR & CHANGES TO TECH SPECS.

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
ACTION:	05 BC ORB#4	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIFL	1	1
	16 FEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 COLLINS	0	0	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 HOUSTON	0	0
	26 VOLLMER	1	1	E JORDAN/IE	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	27 ACRS	16	16			

JAN 25 1979

AOH

TOTAL NUMBER OF COPIES REQUIRED: LTR 43 ENCL 43