

Central File

DUKE POWER COMPANY
ATLANTA, GEORGIA
POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

79 JUL 17 A 8:15
July 13, 1979

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII:JPO
50-269
50-270
50-287

Dear Mr. O'Reilly:

With regard to your letter dated June 25, 1979 concerning IE Bulletin 79-13, Duke Power Company will conduct an inspection of feedwater system welds at the next outage of sufficient duration for each Oconee unit. It is anticipated that this will be the refueling outage for Unit 1 in October, 1979, the refueling outage for Unit 2 in November, 1979, and the refueling outage for Unit 3 in June 1980. A description of this program will be provided for your information prior to the conduct of the inspections. Our response to items 5b, c will be provided on or before July 23, 1979.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr. *By [Signature]*

RLG:scs

*002
CP*

cc: Director
Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

7908070815