

Central File
50-269
270
287

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

September 7, 1979

19 SEP 17 7 12
TELEPHONE AREA 704
373-4082

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII:JPO
50-269
50-270
50-287

Dear Mr. O'Reilly:

With regard to my letter of August 24, 1979 which submitted a response to IE Bulletin 79-05C, the following additional information is provided for Item 4 of the response.

Appropriate emergency procedures have been revised and all licensed reactor operators and senior reactor operators on shift have been initially trained on the new guidelines. Further training will be accomplished as part of the operator training program.

Very truly yours,

William O. Parker, Jr.

William O. Parker, Jr.

7910020203

AO2
190496 KB
OFFICIAL COPY