

*Centrifile*

50-269  
270  
387

USNRC REGION II DUKE POWER COMPANY  
ATLANTA, GEORGIA POWER BUILDING  
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

JAN 28 AIO: 25

January 24, 1980

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: RII:JPO  
50-269  
50-270  
50-287  
IE Bulletin 79-14

Dear Sir:

Please find attached an update of the information provided to your office on October 29, 1979, November 6, 1979 and December 7, 1979 in response to IE Bulletin 79-14. The update includes a summary of the seismic input nonconformance through January 8, 1980. This constitutes, except for possible minor revisions, completion of Items 2 and 3 for Units 1 and 3 and Item 2 of Unit 2. Item 3 for Unit 2 will be completed during the upcoming refueling outage.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr.

KRW:scs

Attachment

T

8002120046

8059 A<sub>2</sub>  
OFFICIAL COPY