

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

TIC
50-269
570
287

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

June 27, 1980 JUL 7 A 9:41

TELEPHONE: AREA 704
373-4063


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII:JPO
50-269
50-270
50-287
IE Bulletin 79-13

Dear Sir:

The hanger inspection required by the subject bulletin was inadvertently not addressed in our correspondence responding to the bulletin. The hangers have been visually inspected as part of our efforts with regard to IE Bulletins 79-02 and -14. Resolution of any discrepancies are being addressed as part of that program. Our response to this area is therefore covered by our correspondence on IE Bulletin 79-02 and -14.

Very truly yours,


William O. Parker, Jr.

KRW:scs



OFFICIAL COPY

8007220192