

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 30, 1980

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: Oconee Unit 1
Docket No. 50-269

Dear Mr. O'Reilly:

My letter of July 11, 1980, which submitted Reportable Occurrence Report RO-269/80-17, indicated that the corrective actions were still under review and evaluation. This Reportable Occurrence Report concerned the removal of the Concentrated Boric Acid Storage Tank (CBAST) pump from service for preventive maintenance, which placed Oconee 1 in a degraded mode of operation per Technical Specification 3.2.2. The review of the corrective actions to prevent a reoccurrence of this incident has been completed and are presented below.

The Oconee Technical Specifications will be reviewed and, if necessary, revised to allow preventive maintenance on plant equipment without being reportable. This review will, of course, consider the safety implications of removing the equipment from service and will evaluate the adequacy of redundant systems in fulfilling the designed function of the equipment while it is out-of-service. Until this review of the Technical Specifications is completed, administrative controls and procedure changes will be implemented to require a condition of cold shutdown for preventive maintenance on the CBAST pumps. In addition, other preventive maintenance procedures involving equipment specified in the Technical Specifications will be reviewed for similar conflicts and revised if necessary.

Very truly yours,


William O. Parker, Jr.

FTP:scs

cc: Director, Office of Management & Program Analysis
Mr. Bill Lavalley (NSAC)

8008050333

S

A002
S 1/0

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8008050333 DOC.DATE: 80/07/30 NOTARIZED: NO
 FACIL:50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
 AUTH.NAME: PARKER,W.O. AUTHOR AFFILIATION: Duke Power Co.
 RECIP.NAME: O'REILLY,J.P. RECIPIENT AFFILIATION: Region 3, Chicago, Office of the Director

DOCKET #
05000269

SUBJECT: Submits corrective actions for 800711 RO-269/80-17 re removal of concentrated boric acid storage tank pump from svc for preventive maint. Tech Specs will be reviewed & revised to allow preventive maint on plant equipment.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Incident Reports

NOTES: M Cunningham: all amends to FSAR & changes to Tech Specs, 05000269

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
	REID,R.	05	1	FATTELE,M.	2	2
INTERNAL:	A/D COMP&STRUCT		1	A/D ENV TECH		1
	A/D MATL & QUAL		1	A/D OP REACTORS		1
	A/D PLANT SYS		1	A/D RAD PROT		1
	A/D SFTY ASSESS		1	A/D TECHNOLOGY		1
	ACC EVAL BR		1	AEOD	10	1
	AUX SYS BR		1	CHEM ENG BR		1
	CONT SYS BR		1	CORE PERF BR		1
	D/DIR,HUM FAC S		1	DIR,ENGINEERING		1
	DIR,HUM FAC SFY		1	DIR,SYS INTEG		1
	EFF TR SYS BR		1	EMERG PREP		1
	EQUIP QUAL BR		1	GEOSCIENCES		1
	HUM FACT ENG BR		1	HYD/GEO BR		1
	I&C SYS BR		1	I&E	09	2
	JORDAN,E./IE		1	LIC GUID BR		1
	LIC QUAL BR		1	MATL ENG BR		1
	MECH ENG BR		1	MPA	11	3
	NRC PDR	02	1	OP EX EVAL BR		3
	OR ASSESS BR		1	POWER SYS BR		1
	PROC/TST REV BR		1	QA BR		1
	RAD ASSESS BR		1	REACT SYS BR		1
	<u>REG FILE</u>	01	1	REL & RISK A BR		1
	SFTY PROG EVAL		1	SIT ANAL BR		1
	STRUCT ENG BR		1	SYS INTERAC BR		1
EXTERNAL:	ACRS		16	LPDR	03	1
	NSIC	04	1	TERA:DOUG MAY		1

AUG 7 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 82 ENCL 0