

A002

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-270 OCONEE 2
RECIPIENT: O'REILLY, J.P.
ORIGINATOR: PARKER, W.O.
COMPANY NAME: DUKE PWR CO
SUBJECT:

DOC DATE: 781122
ACCESSION NBR: 7811300172
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+2

LER#78-011/03L-0 on 781023: ES Analog Channel 3 RB Narrow-Range Pressure Transmitter found to be out-of-calibr due to excessive temp/humidity in penetration room. Action taken to minimize effects of excessive conditions.

NOTARIZED

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
REG PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EER	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#4 BC

TOTAL NUMBER OF COPIES REQUIRED:
LTR 42
ENCL 42

DEC 4 1978

NOTES:

NO 4
CCP

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

November 22, 1978


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

RE: Oconee Unit 2
Docket No. 50-270

Dear Mr. O'Reilly:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station
Technical Specifications, please find attached Reportable Occurrence
Report RO-270/78-11.

Very truly yours,



William O. Parker, Jr.

WOP:scd

Attachment

cc: Director, Office of Management Information
and Program Control

REGULATORY DOCKET FILE COPY

A002
5/11

7811300/72