

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

June 21, 1979

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303


REGULATORY DOCKET FILE COPY

Re: Oconee Unit 2
Docket No. 50-270

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-270/79-3. This report is being submitted pursuant to Oconee Nuclear Station Technical Specifications 6.2 and 6.6.2.1.b(1), which concerns an instrument setting found to be less conservative than permitted by Technical Specifications without preventing fulfillment of the functional requirements of the affected systems, and describes an incident which is considered to have no significance with respect to its effect on the health and safety of the public.

Very truly yours,



William O. Parker, Jr.

SRL/sch

Attachment

cc: Director, Office of Management Information
and Program Control



7906260529

A002
5/11