

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  Prime Healthcare Services - Garden City, LLC 6245 North Inkster Road Garden City, MI 48135  REPORT NUMBER(S) 2016-001		2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S)  030-02036	4. LICENSE NUMBER(S)  21-04072-01	5. DATE(S) OF INSPECTION  May 26, 2016	

**LICENSEE:**  
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.



3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-cited violation(s) were discussed involving the following requirement(s):

4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
 (Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Edward F. Harvey		5/26/16
BRANCH CHIEF	Amos T. McCraw		6/13/16

## Docket File Information

## SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Prime Healthcare Services - Garden City, LLC  
6245 North Inkster Road  
Garden City, MI 48135

REPORT NUMBER(S) 2016-001

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-02036

4. LICENSE NUMBER(S)

21-04072-01

5. DATE(S) OF INSPECTION

May 26, 2016

6. INSPECTION PROCEDURES USED

87131

7. INSPECTION FOCUS AREAS

3.01-3.07

## SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)

02120

2. PRIORITY

3

3. LICENSEE CONTACT

John F. K. Brown, MD

4. TELEPHONE NUMBER

(734) 421-3300

- Main Office Inspection      Next Inspection Date: May 26, 2019
- Field Office Inspection \_\_\_\_\_
- Temporary Job Site Inspection \_\_\_\_\_

## PROGRAM SCOPE

This was a unannounced, routine inspection of a medical institution authorized to use byproduct materials for diagnostic and therapeutic medical procedures under 10 CFR 35.100, 35.200, 35.300, and 35.400. The licensee's Nuclear Medicine Department routinely conducts a weekly average of 10-20 patient studies with one full-time and one part-time nuclear medicine technologist. The majority of diagnostic studies are cardiac tests using Myoview; however, the licensee performs a full spectrum of studies as needed. Although authorized, no iodine-131 procedures or other therapeutic radiopharmaceuticals requiring a written directive have been administered since the previous two inspections. The licensee receives unit doses and multi-dose vials from a local nuclear pharmacy. The licensee is also authorized for low dose brachytherapy procedures and the licensee performs only cesium-137 implant procedures and averages one case per year. Implant procedures are performed by the authorized user and medical physicist from Radiation Therapy Associates, P.C., 6255 North Inkster Road, Garden City, MI

The inspector observed nuclear medicine staff demonstrate package receipt and surveying procedures, daily dose calibrator constancy checks, daily surveys, and waste disposal procedures. There were no patient procedures scheduled on the day of the inspection; however the technologist demonstrated adequate knowledge of radiation protection principles, patient identity verification, and emergency procedures in the event of a spill when explaining the administration process to the inspector.

The inspector reviewed a selection of licensee records, including program audits, dose calibrator linearity records, dose calibrator accuracy records, source inventories, survey meter calibration records, package receipt logs, radiation safety committee meeting minutes, and dosimetry. The highest reported dose since the last inspection was 289 mrem DDE and 293 SDE.

Note to inspector: Radiation Therapy Associates, P.C., 6255 North Inkster Road, Garden City, MI, 21-26536-01, 030-33353, should be inspected concurrently with Prime Healthcare Services - Garden City.

No violations were identified during this inspection.