

CHARLOTTE HUNGERFORD HOSPITAL
P.O. Box 988
540 Litchfield Street
Torrington, CT 06790-0988
Tel: 860-496-6000

June 29, 2016

Nuclear Regulatory Commission
Region I
Nuclear Materials Safety Branch
Division of Radiation Safety and Safeguards
2100 Renaissance Blvd, Suite 100
King of Prussia, PA 19406-2713

Br.1

REC RG 1 07 05 '16 AM 05:55

REFERENCE: Amendment to License Number 06-08349-04 / *103009293*

To Whom It May Concern:

We have replaced our Siemens Ecat PET scanner with a Siemens Briographe TrueVision 64 PET/CT unit. The previous Ge-68 sealed sources used for calibration (Sanders Medical Products Model PET-XXX/YY and Dupont Pharmaceutical Model NES-8429) have been returned to the manufacturer for disposal.

We wish to add the following new Ge-68 sealed sources as follows:

1. Model: Siemens Biogr. TruV Sources, ANSI Classification 97C32312, LS Line Sources encased in stainless steel.
Allowed activity of 5 mCi per source and total of 20 mCi.
2. Model: Siemens Biogr. TruV Sources, ANSI Classification 97C22212, ISO 99/C22212(1), solid matrix encased in high density polyethylene cylinder .
Allowed activity of 5 mCi per source and total of 10 mCi.

Thank you for your prompt attention to this matter.

Sincerely,


Daniel McIntyre
President & CEO

591434
NMSS/RGNI MATERIALS-002



ACKNOWLEDGEMENT - RECEIPT OF CORRESPONDENCE

Name and Address of Applicant and/or Licensee Charlotte Hungerford Hospital ATTN: Daniel McIntyre, Pres. & CEO 540 Litchfield Street P. O. Box 988 Torrington, CT 06790-0988	Date July 18, 2016
	License Number(s) 06-08349-04
	Mail Control Number(s) 591434
	Licensing and/or Technical Reviewer or Branch Medical Branch (Branch 1)

This is to acknowledge receipt of your: Letter and/or Application Dated: 06/29/2016

The initial processing, which included an administrative review, has been performed.

Amendment Termination New License Renewal

There were no administrative omissions identified during our initial review.

This is to acknowledge receipt of your application for renewal of the material(s) license identified above. Your application is deemed timely filed, and accordingly, the license will not expire until final action has been taken by this office.

Your application for a new NRC license did not include your taxpayer identification number. Please complete and submit NRC Form 531, Request for Taxpayer Identification Number, located at the following link: <http://www.nrc.gov/reading-rm/doc-collections/forms/nrc531.pdf>
Follow the instructions on the form for submission.

The following administrative omissions have been identified:

Your application has been assigned the above listed MAIL CONTROL NUMBER. When calling to inquire about this action, please refer to this control number. Your application has been forwarded to a technical reviewer. Please note that the technical review, which is normally completed within 180 days for a renewal application (90 days for all other requests), may identify additional omissions or require additional information. If you have any questions concerning the processing of your application, our contact information is listed below:

Region I
U. S. Nuclear Regulatory Commission
Division of Nuclear Materials Safety
2100 Renaissance Boulevard, Suite 100
King of Prussia, PA 19406-2713
(610) 337-5260, (610) 337-5313,
(610) 337-5398, or (610) 337-5239