



JUL 12 2016

L-2016-138
10 CFR 50.55a

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555-00001

Re: Turkey Point Unit 4
Docket No. 50-251
Inservice Inspection Program
Owner's Activity Report (OAR-1)

Attached find the Owner's Activity Report (Form OAR-1), for Turkey Point Unit 4 Fifth Inservice Inspection Interval, First Period, Second Outage (PTN 4-29). The Form OAR-1, Owner's Activity Report, implements Code Case N-532-4.

Should there be any questions concerning this report, please contact Mr. Mitch Guth, Licensing Manager, at 305-246-6698.

Sincerely,

A handwritten signature in black ink, appearing to read 'T. Summers', with a long horizontal line extending to the right.

Thomas Summers
Vice President
Turkey Point Nuclear Plant

SM
Attachment

cc: Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

A047
NRR

FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number: ISI-PTN-4-2016

Plant: Turkey Point Nuclear Power Plant Unit 4
9760 SW 344th Street
Homestead, Florida 33035

Commercial Service Date: September 7, 1973 Refueling Outage No.: PTN 4-29

Current Inspection Interval: ISI-Fifth IWE-Second

Current Inspection Period: ISI Fifth Interval-First and IWE-Third

Edition and Addenda of Section XI applicable to the inspection plans: ISI Fifth Interval-2007 Edition with Addenda through 2008 and IWE-2001 with Addenda through 2003.


Date and Revision of inspection plans: ISI Fifth Interval Effective-January 21, 2015 Rev.0 and IWE-April 5, 2016, Rev.1

Edition and Addenda of Section XI applicable to repairs and replacements, if different than the inspection plan: ASME Section XI 2007 Edition through 2008 Addenda

Code Cases Used: Approved Code Cases listed in Inspection Plan

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of PTN4-29 conform to the requirements of Section XI.

Signed  ROGER FLEET, FLEET PROGRAM ENGINEERING MGR Date 6/22/16
Owner or Owner's Designee, Title

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of Georgia and employed by the Hartford Steam Boiler Inspection and Insurance Company of Connecticut have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the inspector nor his employer shall be liable in any manner for any personal injury or property damage or loss of any kind arising from or connected with this inspection.

 Commissions NB14292 A,N,I GEORGIA 983 (GA)
Inspector's Signature National Board, State, Province and Endorsements

Date 06/24/2016

FORM OAR-1 OWNER'S ACTIVITY REPORT

**TABLE 1
ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED
EVALUATION FOR CONTINUED SERVICE**

Examination Category and Item Number	Item Description	Evaluation Description
None	None	None

FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 2				
ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE				
Code Class	Item Description	Description Of Work	Date Completed	Repair/Replacement Plan Number
1	Steam Generator 4E210A	Replace Bolt	04/25/2016	RR40350540-01
1	Steam Generator 4E210B	Install Tube Plug	04/25/2016	RR40350547-01
1	Snubber 4-1053	Replace bolting on support	04/08/2016	RR40364134-36
1	Safety Valve RV-4-551B	Replace one stud and nut	04/25/2016	RR40365695-01
1	Piping at Pen-11	Prep for NDE	04/14/2016	RR40459962-01
2	Piping 4P200A	Modify piping for RCP modification	04/25/2016	RR40273327-18
2	Piping 4P200B	Modify piping for RCP modification	04/25/2016	RR40361761-18
2	Piping 4P200C	Modify piping for RCP modification	04/25/2016	RR40361762-21
2	Control Valve CV-4-303A	Replace Bolting	04/25/2016	RR40273327-26

FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 2 ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE				
Code Class	Item Description	Description Of Work	Date Completed	Repair/Replacement Plan Number
2	Control Valve CV-4-303B	Replace Bolting	04/25/2016	RR40361761-26
2	Control Valve CV-4-303C	Replace Bolting	04/25/2016	RR40361762-26
2	Support 4P214B	Cut and weld support	04/09/2016	RR40365364-06
2	Relief Valve RV-4-1403	Replace Bolting	04/25/2016	RR40303578-01
2	Snubber Support 4-1105, 4-1106	Modify Support	04/21/2016	RR40343601-01
2	Snubber Support 4-1105, 4-1106	Replace Snubbers	04/21/2016	RR40459254-01
2	Relief Valve RV-4-1407	Replace Bolting	04/25/2016	RR40350593-01
2	Flange FE-4-127	Replace Bolting	04/25/2016	RR40368049-01
2	Valve CV-4-2902	Replace Bolting	04/25/2016	RR40366792-01
2	Containment Spray Full-Flow Recirculation Piping	Cut and Reroute piping during CCW modification	03/24/2016	RR40369651-54

FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 2				
ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE				
Code Class	Item Description	Description Of Work	Date Completed	Repair/Replacement Plan Number
3	Heat Exchanger 4E207A	Retube and bolting replacement	03/12/2015	RR40088999-01
3	Heat Exchanger 4E207C	Replace Bolting	12/24/2015	RR40397457-02
3	Heat Exchanger 4E207B	Replace Bolting	01/15/2016	RR40434157-01
3	Heat Exchanger 4E207C	Retube and bolting replacement	04/10/2015	RR40089001-01
3	Tank 4T8	Fukushima Modification, Add Emergency Connection	11/25/2014	RR40318922-05
3	Piping Flange ICW Crawl-thru Flanges	Replace Bolting	04/21/2016	RR40350677-01
3	Piping Flange ICW Crawl-thru Flanges	Replace Bolting	04/21/2016	RR40350677-10