

From: Debbie - Gmail [REDACTED]
Sent: Thursday, July 21, 2016 2:00 PM
To: Bower, Fred <Fred.Bower@nrc.gov>
Subject: [External_Sender] RE: Re: NextEra - Seabrook's ASR [2016-SST-0548] and Apparent Assertion(s) of NRC Staff Misconduct

Hello Fred,

Thank you for responding to me today. Also, I am pleased that our communication misunderstanding is cleaned up!

C-10 has still not seen any data or measurements on Seabrook's "wide and discrete cracking" in containment in interior and external walls in NRC documentations made public. What are they?

What is the NRC definition clearly stated of Seabrook's "wide and discrete cracking"?

Also, What are the measurement of the Seabrook's structural "gaps" and the timeframe list of measurements done and to the most current one to know the rate of progressive ASR's impact on concrete deficiencies over years unknown before ASR was discovered?

Thank You,

Debbie