70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA Tel: +82-42-870-5400 / Fax: +82-42-870-5449 http://www.khnp.co.kr

July 29, 2016 Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco Docket No. 52-046

Division of New Reactor Licensing MKD/NW-16-0816L

Subject: Revised Response to RAI 225-8254 for the Question 12.03-11

References: 1) NRC Request for Additional Information 225-8254, dated September 24, 2105

2) KHNP Letter MKD/NW-16-0122L, Response to RAI 225-8254 for Question 12.03-11, dated February 19, 2016

KHNP is hereby submitting the revised response to RAI 225-8254, dated September 24, 2105. The RAI revised response to Question 12.03-11 is to provide an updated COL applicant number regarding the flow diagram of CCW heat exchanger building drain system to LWMS or turbine generator building sump.

The enclosure provides the revised response to RAI 225-8254 for the Question 12.03-11 (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at ahn.daegeun@khnp.co.kr or 703-388-0592.

Sincerely,

Jae-yong Lee Project Manager

Advanced Reactors Development Laboratory Korea Hydro and Nuclear Power Co., Ltd

Enclosure: Revised Response to RAI 225-8254 for the Question 12.03-11 (Non-Proprietary)



Enclosure

Revised Response to RAI 225-8254 for the Question 12.03-11

(Non-Proprietary)

July 29, 2016