



June 2, 2016

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Per 10 CFR 31.5(c)(8), or corresponding State regulation, please be advised that one or more devices containing radioactive material was transferred from a General Licensee to a Specific Licensee... undertaken to ensure proper disposition of obsolete exit signs. The following information is provided:

From General Licensee:

Republic Airlines, Inc.
555 Air Cargo Way
Milwaukee, WI 53207

To Specific Licensee:

SRB Technologies, Inc.
2580 Landmark Drive
Winston-Salem, NC 27103
336.659.2610
Radioactive Materials License #034-0534-2

Date of Transfer:

May 27, 2016

Description of Devices Transferred:

Aircraft exit signs containing tritium, per the enclosed inventory forms.

If you should have any questions, please contact me.

Respectfully,
Russell Parks

A handwritten signature in dark ink, appearing to read "Russell Parks", is written over the typed name.

Environmental Compliance Manager
Republic Airways Holdings
russell.parks@rjet.com
318-471-2558

Enclosures

Cc: File



June 2, 2016

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Per 10 CFR 31.5(c)(8), or corresponding State regulation, please be advised that one or more devices containing radioactive material was transferred from a General Licensee to a Specific Licensee... undertaken to ensure proper disposition of obsolete exit signs. The following information is provided:

From General Licensee:
Republic Airlines, Inc.
555 Air Cargo Way
Milwaukee, WI 53207

To Specific Licensee:
SRB Technologies, Inc.
2580 Landmark Drive
Winston-Salem, NC 27103
336.659.2610
Radioactive Materials License #034-0534-2

Date of Transfer:
May 27, 2016

Description of Devices Transferred:
Aircraft exit signs containing tritium, per the enclosed inventory forms.

If you should have any questions, please contact me.
Respectfully,
Russell Parks

301.415.0595

Environmental Compliance Manager
Republic Airways Holdings
russell.parks@rjet.com
318-471-2558

Enclosures

Cc: File

FEDERAL NOTIFICATION LETTER

Monday, May 23, 2016

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

Republic Airlines Inc
555 Air Cargo Way
Milwaukee, WI 53207

To Specific Licensee:

SRB Technologies, Inc.
2580 Landmark Drive
Winston-Salem, NC 27103
(336)-659-2610
Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Recycling Box was shipped to Specific Licensee)	5/27/2016
---	-----------

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form.

If there are questions or concerns, please contact me.

Sincerely,

Printed Name:	Sharon Taber
Signature:	Sharon Taber
Phone Number:	

Russell Parks 317-471-2558

FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. DO NOT REMOVE THE LABEL FROM THE SIGN. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

[illegible]

Describe any damaged units:
Please email pictures of damaged signs to
pak.ts@veolia.com

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

GENERATOR CERTIFICATION

Generator Signature:

Sharon Taker

Title: Materials Supervisor

Print Name: _____

Sharon Taber

Date: 5/18/2016

VEOLIA INFORMATION – DO NOT WRITE IN THIS BOX

Date Received _____

5/20/16

Checked in by: Lynn Kacher

Customer Service | Toll Free: 1-888-669-9725 Monday-Friday – 8am to 5pm CST

Tritium Exit Sign Recycling Kit | REV 11/2015



KIT # 1

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. DO NOT REMOVE THE LABEL FROM THE SIGN. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

[illegible]

Describe any damaged units:
Please email pictures of damaged signs to
pak.ts@veolia.com

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

GENERATOR CERTIFICATION	
Generator Signature: <u>Sharon Taber</u>	Title: <u>Materials Supervisor</u>
Print Name: <u>Sharon Taber</u>	Date: <u>5/18/2016</u>

VEOLIA INFORMATION – DO NOT WRITE IN THIS BOX	
Date Received	5/20/16
Checked in by:	Lynn Becker