



KHNP

KOREA HYDRO & NUCLEAR POWER CO., LTD

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

August 8, 2016
Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco
Division of New Reactor Licensing

Docket No. 52-046
MKD/NW-16-0865L

Subject: Revised Response to RAI 182-8160 for the Question 03.07.01-4

References: 1) NRC Request for Additional Information 182-8160, dated August 31, 2015
2) KHNP Letter MKD/NW-15-0411L, Response to RAI 182-8160 for Question 03.07.01-4, dated December 31, 2015

KHNP is hereby submitting a revised response to RAI 182-8160, dated August 31, 2015. The RAI revised response addresses Question 03.07.01-4 to clarify the descriptions in the soil profile and to provide the soil profile used in the SSI analysis for HRHF seismic input motion.

The enclosure provides the revised response to RAI 182-8160 for the Question 03.07.01-4 (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at ahn.daegeun@khnp.co.kr or 703-388-0592.

Sincerely,

Jae-yong Lee
Project Manager
Advanced Reactors Development Laboratory
Korea Hydro and Nuclear Power Co., Ltd

Enclosure: Revised Response to RAI 182-8160 for Question 03.07.01-4 (Non-Proprietary)

Enclosure

Revised Response to RAI 182-8160 for Question 03.07.01-4

(Non-Proprietary)

August 8, 2016