



KHNP

KOREA HYDRO & NUCLEAR POWER CO., LTD

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

August 25, 2016
Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco
Division of New Reactor Licensing

Docket No. 52-046
MKD/NW-16-0921L

Subject: Revised Response to RAI 252-8299 for the Question 03.07.02-9

References: 1) NRC Request for Additional Information 252-8299, dated October 19, 2015
2) KHNP Letter MKD/NW-16-0027L, Response to RAI 252-8299 for Question 03.07.02-9, dated January 12, 2016

KHNP is hereby submitting a revised response to RAI 252-8299, dated October 19, 2015. The revised response addresses Question 03.07.02-9 to clarify that the seismic response of the EDGB/DFOF are revised due to modification of the SSI analysis model for three rock type soil profiles at ground surface.

The enclosure provides the revised response to RAI 252-8299 for the Question 03.07.02-9 (Non-Proprietary).

If additional information or clarification is required, please contact Daeyeun Ahn, Director of KHNP Washington DC Center at ahn.daeyeun@khnp.co.kr or 703-388-0592.

Sincerely,

Jae-yong Lee
Project Manager
Advanced Reactors Development Laboratory
Korea Hydro and Nuclear Power Co., Ltd

Enclosure: Revised Response to RAI 252-8299 for Question 03.07.02-9 (Non-Proprietary)

Enclosure

Revised Response to RAI 252-8299 for Question 03.07.02-9

(Non-Proprietary)

August 25, 2016