



SMUD

SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

September 21, 1979

Mr. D. F. Ross Jr., Director
Bulletins and Orders Task Force
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Docket No. 50-312
Rancho Seco Nuclear Generating
Station- Unit No. 1

Dear Mr. Ross,

Your letter of August 21, 1979 requested information on several items. Item 2 of enclosure 1 to your letter requested verification that operator training and drilling at Rancho Seco Unit 1 incorporates the necessary Lessons Learned from TMI-2.

The District's Administrative Procedure No. AT25, "License NRC Operator Retraining" has been upgraded and now requires the TMI-2 Incident and Lessons Learned from that incident to be subjects of regular operator training lecture series. If we can provide any further details of our training program, please advise.

Sincerely yours,

John J. Mattimoe
Assistant General Manager
and Chief Engineer

Handwritten:
A001
5/10
ADD:
DROSS
RCAPRA

7909250 474
79082500