

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 11, 1980

TELEPHONE: AREA 704
373-4083


Mr. J. P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Oconee Unit 1
Docket No. 50-269

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-269/80-21. This report is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.b(2), which concerns operation in a degraded mode permitted by a limiting condition for operation, and describes an incident which is considered to be of no significance with respect to safe operation or its effect on the health and safety of the public.

Very truly yours,



William O. Parker, Jr.

FTP:scs
Attachment

cc: Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
P. O. Box 10412
Palo Alto, California 94303

A002
7/11

8007210417

S