

DUKE POWER COMPANY

POWER BUILDING  
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

RECEIVED DISTRIBUTION  
SERVICES UNIT

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

November 10, 1980

1980 NOV 13 4PM 42 '26

TELEPHONE: AREA 704  
373-4083

US NRC  
DISTRIBUTION SERVICES  
BRANCH

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

Re: Oconee Nuclear Station  
Docket No. 50-269

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-269/80-33. This report is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.b(2), which concerns operation in a degraded mode permitted by a limiting condition for operation, and describes an incident which is considered to be of no significance with respect to its effect on the health and safety of the public.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr. *WOP*

WOP:ls  
Attachment

cc: Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
P.O. Box 10412  
Palo Alto, California 94303

*1002  
5/11*

801114037a

\$