

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7812190127 DOC. DATE: 78/12/11 NOTARIZED: NO DOCKET # 05000269
 FACIL: 50-269 OCONEE #1, DUKE POWER CO.
 AUTH. NAME: PARKER, W.O. AUTHOR AFFILIATION: DUKE POWER CO.
 RECIP. NAME: O'REILLY, J.P. RECIPIENT AFFILIATION: **REG. 2, ATLANTA, OFF. OF THE DIRECTOR

SUBJECT: Forwards LER#78-026/03L-0. While attempting to put RBCU 'C' fan into svc, damper-open indication not received in control room. Caused by blown fuse in damper motor circuit.
 DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2
 TITLE: INCIDENT REPORTS

NOTES: M CUNNINGHAM - All AMDIS TO FSAR & CHANGES TO TECH SPECS

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	05 BC ORB#4	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 HANAUER	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 COLLINS	0	0	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 HOUSTON	0	0
	26 VOLLMER	1	1	E JORDAN/IE	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	27 ACRS	16	16			

DEC 20 1978

ccp
A0/I-4

TOTAL NUMBER OF COPIES REQUIRED: LTR 43 ENCL 43

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

December 11, 1978

TELEPHONE: AREA 704
373-4083

REGULATORY DOCKET FILE COPY


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

RE: Oconee Unit 1
Docket No. 50-269

Dear Mr. O'Reilly:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station
Technical Specifications, please find attached Reportable Occurrence
Report RO-269/78-26.

Very truly yours,



William O. Parker, Jr.

KRW:ldh

Attachment

cc: Director, Office of Management Information
and Program Control

7812190127

A002
S/11