

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

April 18, 1979

TELEPHONE: AREA 704
373-4083


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Oconee Unit 1
Docket No. 50-269

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-269/79-11. This report is being submitted pursuant to Oconee Nuclear Station Technical Specifications 6.2 and 6.6.2.1.b(2), which concerns operation in a degraded mode permitted by a limiting condition for operation, and describes an incident which is considered to have no significance with respect to its effect on the health and safety of the public.

Very truly yours,


William O. Parker, Jr.

SRL:scs
Attachment

cc: Director, Office of Management Information
and Program Control



7904240328

A002
5/11

Corrective Action:

The redundant isolation valve outside the Reactor Building was closed in order to assure that containment integrity would be maintained. A loose wire on the valve motor contactor was determined to be the reason for the overheating of the thermal overloads. The wire was tightened, and subsequent testing verified the operability of valve PR-7 well within four hours of discovering its inoperability. The isolation valves were then opened, restoring the gaseous monitoring systems to service.

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7905140373 DOC. DATE: 79/04/13 NOTARIZED: NO
 FACIL: 50-269 OCONEE NUCLEAR STATION, UNIT 1, DUKE POWER CO.
 AUTH. NAME AUTHOR AFFILIATION
 PARKER, W.O. DUKE POWER CO.
 RECIP. NAME RECIPIENT AFFILIATION
 O'REILLY, J.P. REGION 2, ATLANTA, OFFICE OF THE DIRECTOR

DOCKET #
05000269

SUBJECT: DESCRIBES RO-269/79-10 WHICH WAS TO HAVE BEEN SUBMITTED ON
 790413 RE REMOVAL OF HIGH PRESSURE SVC WATER PUMP FROM SVC
 AS RESULT OF LEAKAGE FROM MOTOR CODER. COOLER REPAIRED &
 RETURNED TO SVC.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: INCIDENT REPORTS

NOTES: M. Cunningham - All Amendments to FSAR + changes to

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES		Tech Specs
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL	
	05 BC ORB #4	4					
INTERNAL:	01 REG FILE	1		02 NRC PDR	1		
	09 I&E	2		11 MPA	3		
	14 TA/EDO	1		15 NOVAK/KNIEL	1		
	16 EEB	1		17 AD FOR ENGR	1		
	18 PLANT SYS BR	1		19 I&C SYS BR	1		
	20 AD PLANT SYS	1		21 AD SYS/PROJ	1		
	22 REAC SAFT BR	1		23 ENGR BR	1		
	24 KREGER	1		25 PWR SYS BR	1		
	26 AD/SITE ANAL	1		27 OPERA LIC BR	1		
	28 ACCIDENT ANLYS	1		29 AUX SYS BR	1		
	E JORDAN/IE	1					
EXTERNAL:	03 LPDR	1		04 NSIC	1		
	29 ACRS	16					

A04
CCP

MAY 16 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 46 ENCL 0