ellan

1981 OCT 25 A 9:

5

Docket Nos. 50-269, 50-270, 50-287 License Nos. DPR-38, DPR-47, DPR-55

Duke Power Company ATTN: Mr. H. B. Tucker, Vice President Nuclear Production Department 422 South Church Street Charlotte, NC 28242

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-269/87-37, 50-270/87-37 AND 50-287/87-37

OCT 1 6 1987

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by J. L. Coley on September 18 and September 21-24, 1987. The inspection included a review of activities authorized for your Oconee facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is invited to the unresolved item identified in the inspection report. This matter will be pursued during future inspections.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely, DRIGINAL SIGNED BY ALAN R. HERDT Alan R. Herdt, Chief Engineering Branch Division of Reactor Safety

8710270001 871016 PDR ADUCK 05000269 Q PDR

Enclosure: NRC Inspection Report

cc w/encl: M. S. Tuckman, Station Manager

bcc w/encl: NRC Resident Inspector H. Pastis, NRR State of South Carolina

RII XC JColey:1b 10/14/87

ake /14∕/87

RII // **TPeebles** 10//5/87

TEFT