



KHNP

KOREA HYDRO & NUCLEAR POWER CO., LTD

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

October 24, 2016
Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco
Division of New Reactor Licensing

Docket No. 52-046
MKD/NW-16-1052L

Subject: Revised Response to RAI 356-7881 for Question 07-18

References: 1) NRC Request for Additional Information 356-7881, dated January 4, 2016
2) KHNP Letter MKD/NW-16-0388L, Response to RAI 356-7881 for Questions 07-3, 07-5, 07-8, 07-13, 07-14, 07-16, and 07-18, dated May 5, 2016

KHNP is hereby submitting the revised response to RAI 356-7881, dated January 4, 2016. The revised response addresses Question 07-18 on failure identification of the QIAS-N and IFPD portion of the I&C system, as well as the information on the workstation disable switch. The enclosure provides the revised response to RAI 356-7881 for Question 07-18 (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at ahn.daegeun@khnp.co.kr or 703-388-0592.

Sincerely,

Jae-yong Lee
Project Manager
Advanced Reactors Development Laboratory
Korea Hydro and Nuclear Power Co., Ltd

Enclosure: Revised Response to RAI 356-7881 for Question 07-18 (Non-Proprietary)

Enclosure

Revised Response to RAI 356-7881 for Question 07-18

(Non-Proprietary)

October 24, 2016