U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

#### REGION V

Report No.	50-275/79-02			•
Docket No.	50-275	License No.	CPPR-39	Safeguards Group
Licensee:	Pacific Gas and Elect		¥	
•	77 Beale Street			•
	San Francisco, Califo	ornid 94106		
Facility Na	ame: Diablo Canyon	Unit 1		
Inspection	at: Diablo Canyon	Site, San Luis	Obispo County	, California ′
Inspection	conducted: January11	-31, 1979		
Inspectors	N / N M M	V		2/8/79
	T. Young, Jr., Resid	lent keadtor In	spector	/ Date Signed
**/		The second free and free and a second control of the second contro		Date Signed
Approved By	OM. Hern	berg.	•	Date Signed $2/8/79$
	D. M. Sternberg, Chi Reactor Operations a			l Date Signed .
Summary:	Inspection on January	1-31, 1979 (Re	eport No. 50-27	5/79-02)

Areas Inspected: Routine inspection of preoperational testing, fire prevention/protection, environmental protection, plant tour and witnessing of testing in progress. This inspection involved 98 inspector-hours onsite by one NRC resident inspector.

Results: No items of noncompliance or deviations were identified.

vocalectory

### **DETAILS**

### 1. Persons Contacted

- \*R. D. Ramsay, Plant Superintendent
- R. D. Etzler, Project Superintendent
- \*M. N. Norem, Resident Startup Engineer
- \*M. E. Leppke, Q.A. Supervisor
- \*J. S. Diamonon, Q.C. Supervisor
- \*R. Patterson, Supervisor of Operations
- \*D. A. Backons, Supervisor of Maintenance
  - J. M. Gisclon, Power Plant Engineer

The inspector also talked with and interviewed a number of other licensee employees, including members of general construction, the operations staff and Q.A. organization personnel.

\*Denotes those attending the exit interview.

### 2. Organization

Mr. Warren Raymond is replacing Mr. Russell Wischow as director of quality assurance effective February 1, 1979.

## 3. Fire Protection/Prevention


The control room and the cable spreading rooms were inspected. The fire alarm, extinguishing equipment, actuating controls and fire fighting equipment were verified to be operable in the cable spreading rooms and 25% of the balance of the plant. The modification of cable penetration seal material was verified not to be flammable.

No items of noncompliance or deviations were identified.

# 4. <u>Environmental Protection</u>

The inspector verified by direct observation that all of the air particulate and charcoal filter sampling stations as described in the FSAR are installed and operating. The air particulate samples are routinely collected on a weekly basis and the film badges and TLD measurements are made on a monthly basis.

No items of noncompliance or deviations were identified.



## 5. Plant Tour

The inspector walked through various areas of the plant on a weekly basis to observe activities in progress; to inspect the general state of cleanliness, housekeeping and adherence to fire protection rules; to check the proper approval of "Man on the Line, Caution and Clearance" tags on equipment; and to review with operators the status of various systems in the plant.

The inspector noted that the status of the systems and the house-keeping appeared consistent with construction activities.

No items of noncompliance or deviations were identified.


## 6. Preoperational Testing

a. Portions of the following tests were witnessed by the inspector:

8.3.3.	Boron Addition and Control		
23.3	Preoperational Testing of Auxiliary and Fuel Handling Building Ventilation		
24.3	Purge Gaseous Radwaste		
25.6	Containment Class I Instrument Air Performance Demonstration		
37.10	Steam Dump Performance Demonstration		
21.2 A-1	Reflush Diesel Fuel Oil System Lines		

b. While witnessing the above testing (in some tests only parts of the tests were being performed or redone), the inspector verified that the procedures were technically adequate; the latest revisions were available and approved; the overall crew performance was adequate and, in the case of completed tests, the acceptance criteria were met. Administrative controls for design change and documentation were followed.

No items of noncompliance or deviations were identified.



## c. Regulatory Guide 1.68.2

(50-275/78-14)(Closed) The licensee is planning to demonstrate the new requirements of this guide (Paragraph C.4) "Cold Shutdown Demonstration" during system verification testing. A procedure has been written and currently is in draft form. This item is considered closed.

No items of noncompliance or deviations were identified.

## 7. Exit Interview

The inspector met with a senior licensee representative on a weekly basis and with the representatives denoted in Paragraph 1 on the last friday in the month on January 26, 1979. The scope and findings of the inspection were summarized by the inspector.

S. Carlot • . •