

PACIFIC GAS AND ELECTRIC COMPANY

PG=E +

P. O. BOX 7442 • 77 BEALE STREET, 31ST FLOOR, SAN FRANCISCO, CALIFORNIA 94106 TELEPHONE (415) 781-4211 TELECOPIER (415) 543-7813

April 7, 1981

RELATED CORRESPONDENCE

Mr. R. H. Engelken, Director Office of Inspection and Enforcement Region V U. S. Nuclear Regulatory Commission 1990 N. California Boulevard Walnut Creek Plaza, Suite 202 Walnut Creek, CA 94596

Re: Docket No. 50-275

Docket No. 50-323

Diablo Canyon Units 1 and 2

Subject: IE Bulletin 80-21, "Valve Yokes Supplied by

Malcolm Foundry Company Inc."

Dear Mr. Engelken:

A response to the subject bulletin was provided in our letter to you dated January 21, 1981. At that time we had determined that the Diablo Canyon Units have no valves made by Anchor/Darling Valve Company utilizing Malcolm Foundry products.

To date we have determined that none of the safety related control valves utilized in the Diablo Canyon Project used parts cast by Malcolm Foundry. Furthermore, no Westinghouse supplied valves utilized Malcolm Foundry parts.

At the present time we are reviewing the status of manually operated valves for use in safety-related systems. We are determining

DS03







1

-

COPY

Mr. R. H. Engelken

-2-

April 7, 1981

if any of these active valves have parts cast by the Malcolm Foundry Company Inc. This review should be complete by May 15, 1981.

Very truly yours,

Philip A. Crane, Jr.

CC: Director
Office of Inspection and Enforcement
Division of Reactor Construction Inspection
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Bart Buckley, Project Manager Nuclear Regulatory Commission 7920 Norfolk Avenue Bethesda, MD 20114

Service List

, ` • , • •