REGULATOR INFORMATION DISTRIBUTION TEM (RIDS)

ACCESSION NBR:8310200144 DOC.DATE: 83/10/14 NOTARIZED: NO DOCKET # FACIL:50-275 Diablo Canyon Nuclear Power Plant, Unit 1, Pacific Ga 05000275

"AUTH.NAME" AUTHOR AFFILIATION

SCHUYLER, J.O. Pacific Gas & Electric Co.

RECIPIENT AFFILIATION EISENHUT, D.G. Division of Licensing

SUBJECT: Submits add) info on App R review re schedule for fire door mods. Installation of directional closed head sprinkler protection on both sides of panels & transoms suggested.

DISTRIBUTION CODE: BOO2S COPIES RECEIVED:LTR __ ENCL _O SIZE:_______TITLE: Licensing Submittal: Fire Protection

NOTES: J Hanchett 1cy PDR Documents.

05000275

	RECIPIENT IĎ CODEZNAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL	
	NEE TB3 BC		1	4	schierling,	1 01	1	1)
INTERNAL:	ELD/HDS2 NRR/DE/CEB REG_EILE	06 04	1 2 1	d 2 1	IE FILE NRR/DSI/ASB RGN5	07	1 1 1	
EXTERNAL:	ACRS NRC PDR NTIS	10 02	6 1 1	511	LPDR NSIC	03 05	1	2
NOTES:			1	i i				•

•

ж ж ж

PACIFIC GAS AND ELECTRIC COMPANY

PG=E -- 77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

J. O. SCHUYLER
VICE PRESIDENT
NUCLEAR POWER GENERATION

October 14, 1983

Mr. Darrell G. Eisenhut, Director Division of Licensing Office of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Washington, D.C. 20555

Re: Docket No. 50-275, OL-DPR-76
Diablo Canyon Unit 1
Additional Information on Appendix R Review
Schedule for Fire Door Modifications

Dear Mr. Eisenhut:

In an October 11, 1983 letter, PGandE provided the schedule for completion of the modification of fire doors.

The following actions or combinations of actions are currently being considered as possible options for modifications of side panels and transoms which cannot meet UL approved configurations:

- (1) Install additional labeled rolling fire doors or double fire door assemblies to protect or replace the existing panels and transoms.
- (2) Replace or modify the existing panels and transoms with an approved configuration consistent with the fire rating of the barrier. This may require restructuring the panel assemblies with new frames and new panels.
- (3) Provide directional closed head sprinkler protection on both sides of the panels and transoms.
- (4) Utilize other approved fire resistive configurations complying with applicable portions of Appendix R Section III.G.

Kindly acknowledge receipt of this material on the enclosed copy of this letter and return it in the enclosed addressed envelope.

Sincerely,

J. G. Schusler fam

J. O. Schuyler

8310200144 831014 PDR ADOCK 05000275 F PDR

cc: Service List

13002