REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8503110204 DUC.DATE: 85/03/05 NOTARIZED: NO DOCKET # FACIL:50=275 Diablo Canyon Nuclear Power Plant, Unit 1, Pacific Ga 05000275

AUTH.NAME AUTHOR AFFILIATION

SHIFFER, J.D. Pacific Gas & Electric Co.

RECIP.NAME. RECIPIENT AFFILIATION EISENHUT, D.G. Division of Licensing

SUBJECT: Part 21 rept re fire dampers w/closure springs supplied by Ruskin Mfg Co.Deficiency identified in vendor 841106 Part 21 rept.Dampers being tested to evaluate possible closure problems under air flow conditions.

NOTES: J Hanchett 1cy PDR Documents. OL:09/22/81 05000275

	RECIPIENT ID CODE/NAME NRR LB3 BC 01		COPIES LTTR ENCL 3 3		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL	
INTERNAL:	ACRS ELD/HDS2 NRR HOLONICH NRR/DE/GEB REG FILE	11 07 09 04	3 1 2 2	MONNI	ADM/LFMB IE WHITNEY,L NRR WAMBACH NRR/DL DIR RGN5	06	1 1 1 1	1 0 1 1
EXTERNAL:	LPDR NSIC	03 05	2	2	NRC POR	02	1	∤· `.
NOTES:			1	1				

To the second se RANGE DE LA FIRM DE LA SECULIA DEL LA SEC

•

 $\mathbf{S}_{i} = \mathbf{0}$

PACIFIC GAS AND ELECTRIC COMPANY

PGWE

+

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

JAMES D. SHIFFER
VICE PRESIDENT
NUCLEAR POWER GENERATION

March 5, 1985

PGandE Letter No.: DCL-85-092

Mr. Darrell G. Eisenhut, Director Division of Licensing Office of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Washington, D.C. 20555

Re: Docket No. 50-275, OL-DPR-80

Diablo Canyon Unit 1

Appendix R Additional Information - Ruskin Fire Damper

Dear Mr. Eisenhut:

PGandE is currently testing fire dampers with closure springs which were supplied by the Ruskin Manufacturing Company and which are installed in Diablo Canyon Unit 1. This testing is being done to evaluate possible closure problems under air flow conditions. These dampers were identified in a 10 CFR 21 report dated November 6, 1984 from Ruskin Manufacturing Company to the NRC. If it is determined that modifications are necessary, they will be of similar types as provided by Ruskin to correct the closure problems of the dampers at Palo Verde Unit 1.

Kindly acknowledge receipt of this material on the enclosed copy of this letter and return it in the enclosed addressed envelope.

Sincerely.

J. D. Shiffer

cc: J. B. Martin
H. E. Schierling
Service List

Aoole No

8503110204 850305 PDR ADDCK 05000275 S PDR

A STATE OF THE STA 1 ť