## ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9110240153 DOC.DATE: 91/10/18 NOTARIZED: NO DOCKET # FACIL:50-323 Diablo Canyon Nuclear Power Plant, Unit 2, Pacific Ga 05000323

AUTH.NAME AUTHOR AFFILIATION

SHIFFER, J.D. Pacific Gas & Electric Co.

RECIP.NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Forwards voluntary LER 91-008-00 re contract radiographer overexposure due to equipment failure & personnel error.

Requirements of 10CFR20.405 inapplicable since source licensed to contractor.Listed LER numbers will not be used.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR \_ ENCL \_ SIZE: \_ \_ TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

## NOTES:

(

	RECIPIENT ID CODE/NAME PD5 LA ROOD,H	COPII LTTR 1 1	ES ENCL 1 1	RECIPIENT ID CODE/NAME PD5 PD	COP LTTR 1	IES ENCL 1
.INTERNAL:	ACNW AEOD/DOA AEOD/ROAB/DSP NRR/DET/EMEB 7E NRR/DLPQ/LPEB10 NRR/DREP/PRPB11 NRR/DST/SICB8H3 NRR/DST/SRXB 8E RES/DSIR/EIB	2 1 2 1 1 1 1	2 1 2 1 2 1 1	ACRS AEOD/DSP/TPAB NRR/DET/ECMB 9H NRR/DLPQ/LHFB10 NRR/DOEA/OEAB NRR/DST/SELB 8D NRR/DST/SELB 8D NRR/DST/SPLB8D1 REG FIEE 02 RGN5 FILE 01	2 1 1 1 1 1 1	2 1 1 1 1 1 1
EXTERNAL:	EG&G BRYCE, J.H NRC PDR NSIC POORE, W.	3 1 1	3 1 1	L ST LOBBY WARD NSIC MURPHY,G.A NUDOCS FULL TXT	1 1 1	1 1 1


NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

1

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 33 ENCL 33



77 Beale Street San Francisco, CA 94106 415/973-4684 TWX 910-372-6587 James D. Shiffer Senior Vice President and General Manager Nuclear Power Generation



October 18, 1991

PG&E Letter No. DCL-91-250

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Re: Docket No. 50-323, OL-DPR-82

Diablo Canyon Unit 2

Licensee Event Report 2-91-008-00, Voluntary

Contract Radiographers Overexposed Due To Equipment Failure and

Personnel Error

## Gentlemen:

PG&E is submitting the enclosed voluntary Licensee Event Report (LER) concerning an overexposure of contract radiographers from a radiography source that occurred at Diablo Canyon Power Plant. Since the radiography source is licensed to the contractor, the requirements of 10 CFR 20.405 are not applicable to PG&E for this event. The event does not meet the reporting criteria of 10 CFR 50.73, and this report is being submitted for information purposes only. Any required reporting in accordance with Title 17 of the California Code of Regulations, including personnel exposure information, is the responsibility of the contractor.

This event has in no way affected the health and safety of the public.


Regarding an unrelated administrative matter, as requested in Section VI of NUREG-1022, PG&E is notifying you that the following LER numbers will not be used:

LER number 1-89-018 for docket 05000275 LER number 1-90-008 for docket 05000275 LER number 1-90-011 for docket 05000275 LER number 1-90-016 for docket 05000275

Sincerely,

James D. Shiffer

9110240153 911018 PDR ADOCK 05000323 S PDR Kegg!



cc:

Ann P. Hodgdon John B. Martin

Phillip J. Morrill Harry Rood Howard J. Wong CPUC

Diablo Distribution

INPO

Enclosure

DC0-91-TC-N080

5518S/85K/JHA/2242

