

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9210260232 DOC. DATE: 92/10/19 NOTARIZED: NO DOCKET #
 FACIL: 50-275 Diablo Canyon Nuclear Power Plant, Unit 1, Pacific Ga 05000275
 AUTH. NAME AUTHOR AFFILIATION
 RUEGER, G.M. Pacific Gas & Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards Special Rept 92-004, listing tubes plugged in each SG during facility fifth refueling outage completed on 921006. Total of 29 SG tubes plugged, as listed.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: OR Submittal: General Distribution

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD5 LA	1 1	PD5 PD	1 1
ROOD, H	2 2		
INTERNAL: ACRS	6 6	NRR/DET/ESGB	1 1
NRR/DOEA/OTSB11	1 1	NRR/DST/SELB 7E	1 1
NRR/DST/SICB8H7	1 1	NRR/DST/SRXB 8E	1 1
NUDOCS-ABSTRACT	1 1	OC/LFMB	1 0
OGC/HDS1	1 0	<u>REG FILE</u> 01	1 1
RES/DSIR/EIB	1 1		
EXTERNAL: NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 20

R
I
D
S
/
A
D
S
/
A
D
S

Pacific Gas and Electric Company

77 Beale Street
San Francisco, CA 94106
415/973-4684

Gregory M. Rueger
Senior Vice President and
General Manager
Nuclear Power Generation

October 19, 1992

PG&E Letter No. DCL-92-227



U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Re: Docket No. 50-275, OL-DPR-80
Diablo Canyon Unit 1
Special Report 92-04, Steam Generator Tube Plugging During 1R5

Gentlemen:

In accordance with the requirements of DCP Technical Specifications 4.4.5.5.a and 6.9.2, this Special Report is submitted to report the number of tubes plugged in each steam generator during the Unit 1 fifth refueling outage (1R5). Tube plugging was completed on October 6, 1992.

A total of 29 steam generator tubes were plugged, as listed below.

SG 1-1: 6 tubes
SG 1-2: 15 tubes
SG 1-3: 4 tubes
SG 1-4: 4 tubes

Of the 29 tubes, 17 are located in short radius rows 1 and 2 and were plugged because of indications in the U-bend region. The other 12 tubes were plugged because of antivibration bar (AVB) wear.

The enclosed table provides the location (row and column) of the plugged tubes.

Sincerely,

A handwritten signature in black ink, appearing to read 'Greg M. Rueger'. The signature is fluid and cursive, with a long horizontal stroke at the end.

Gregory M. Rueger

cc: Ann P. Hodgdon
John B. Martin
Philip J. Morrill
Harry Rood
CPUC
Diablo Distribution

Enclosure

5889S/85K/JHA/2245

9210260232 921019
PDR. ADDCK 05000275
P. PDR



Adol
11/1

1992

ENCLOSURE

DCPP STEAM GENERATOR TUBES PLUGGED DURING 1R5

<u>SG</u>	<u>Row</u>	<u>Column</u>	<u>Reason for Plugging</u>
1-1	1	1	Indication in U-bend
	1	2	Indication in U-bend
	1	58	Indication in U-bend
	39	43	AVB wear
	39	49	AVB wear
	39	50	AVB wear
1-2	1	18	Indication in U-bend
	1	24	Indication in U-bend
	1	43	Indication in U-bend
	1	52	Indication in U-bend
	1	68	Indication in U-bend
	1	71	Indication in U-bend
	1	72	Indication in U-bend
	1	74	Indication in U-bend
	1	90	Indication in U-bend
	1	91	Indication in U-bend
	1	92	Indication in U-bend
	1	93	Indication in U-bend
	34	46	AVB wear
	38	48	AVB wear
	39	52	AVB wear
1-3	1	66	Indication in U-bend
	2	87	Indication in U-bend
	35	59	AVB wear
	37	38	AVB wear
1-4	36	36	AVB wear
	36	54	AVB wear
	39	44	AVB wear
	42	60	AVB wear

Note: All tubes were plugged with solid mechanical plugs.

