## ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATER INFORMATION DISTRIBUTION YSTEM (RIDS)

ACCESSION NBR:9309030203 DOC.DATE: 93/08/27 NOTARIZED: YES DOCKET FACIL:50-275 Diablo Canyon Nuclear Power Plant, Unit 1, Pacific Ga 050002 50-323 Diablo Canyon Nuclear Power Plant, Unit 2, Pacific Ga 050003	н
AUTH.NAME AUTHOR AFFILIATION	75
FUJIMOTO,W.H. Pacific Gas & Electric Co. RECIP.NAME RECIPIENT AFFILIATION Document Control Branch (Document Control Desk)	R
	Ι
SUBJECT: Forwards replacement pages pages for LAR 92-05 re rev to TS & assoc bases to reflect Eagle 21 process protection sys upgrade,elimination of bypass manifolds for reactor coolant	D
sys RTD & assoc enhancements.	S
DISTRIBUTION CODE: A001D COPIES RECEIVED:LTR $\frac{1}{2}$ ENCL $\frac{1}{2}$ SIZE: $\frac{2+12}{2}$ TITLE: OR Submittal: General Distribution	1
ч	
NOTES:	A
RECIPIENT COPIES RECIPIENT COPIES ID CODE/NAME LTTR ENCL ID CODE/NAME LTTR ENCL	A D
RECIPIENT COPIES RECIPIENT COPIES	
RECIPIENTCOPIESRECIPIENTCOPIESID CODE/NAMELTTR ENCLID CODE/NAMELTTR ENCLPDV LA11PDV PD1	D

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 20

D D

R

I

D

S

1

A

S

. .

.

Pacific Gas and Electric Company

Nuclear Technical Services, A10G 333 Market Street, Room 8024 P.O. Box 770000 San Francisco, CA 94177 415/973-0600 Fax 415/973-1427 Warren H. Fujimoto Vice President

August 27, 1993

PG&E Letter No. DCL-93-212

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Re: Docket No. 50-275, OL-DPR-80 Docket No. 50-323, OL-DPR-82 Diablo Canyon Units 1 and 2 Replacement Pages for License Amendment Request 92-05

Gentlemen:

On September 21, 1992, PG&E submitted License Amendment Request (LAR) 92-05 in Letter No. DCL-92-203. The LAR involved proposed revisions to Technical Specifications (TS) 2.2.1, 3/4.3.1, 3/4.3.2, and their associated Bases to reflect the Eagle 21 process protection system upgrade, elimination of the bypass manifolds for the reactor coolant system resistance temperature detectors (RTDs), and associated enhancements.

Replacement pages for some of the original marked-up TS pages included in LAR 92-05 are enclosed. The revisions to the TS are being submitted for clarification or for administrative reasons. An explanation of the revisions to the replacement pages is provided below.

- For TS 3.3.1, Table 3.3-2, Table Notation Insert 0, delete Note 2 regarding the 4.0 second response time for RTDs mounted in thermowells. The note was initially added to provide additional information regarding the RTD response time. However, the note is not necessary to meet TS requirements for instrumentation response times. Additionally, the note can lead to confusion if the 4.0 seconds is interpreted as an acceptance criterion, as well as the 7.0 second criterion for overtemperature delta-T (OTDT) and overpressure delta-T (OPDT) channel response times. Deletion of the note from Table 3.3-2 has no impact on the safety evaluation performed for LAR 92-05, previously submitted on September 21, 1992 (see Safety Evaluation/RTD Response Time, page 15).
- 2. For TS 3.3.2, Table 3.3-3, Functional Unit, Item 1.f, "Steam Line Pressure-Low," correct the table notation for Applicable Modes from "##" to "#". The September 21, 1992, submittal referenced the incorrect table notation. This change is administrative only.
- 3. For TS 3.3.2, Table 3.3-3, Insert R, change Action Statement numbers to Action 29; for Table 3.3-3, Action Statements (Continued), Insert S, change the Action Statement numbers to

9309030203 930827 ADOCK 05000275



· · 

. •

به این . میری بعدین

Action 29 and Action 35, and change the appropriate Functional Units 6.c and 6.d correspondingly. The Action Statements in the Instrumentation Section of the TS have historically been numbered sequentially throughout the whole section for human factors reasons. These changes are administrative only (to preserve the numbering system).

- 4. For TS 4.3.2.1, Table T.3-2, Table Notation Insert Y for Note (3), Replace "may be manually" with "is automatically." This corrects the table notation so that it conforms to descriptions of the P-11 relationship with the steamline pressure protection functions given in the September 21, 1992, submittal. This change is administrative only.
- 5. For Insert K on Bases page B 2-7, for Steam Generator Water Level, replace the parenthetical phrase, "(failure of more than one T, RTD or failure of a T, RTD)," with the nonparenthetical phrase, "to the TTD" to clarify the operation of the Trip Time Delay (TTD) feature. The phrase defining loop delta-T failure is out of context in the discussion of the steam generator water level trip time delay calculation. The loop delta-T channel input to the TTD follows the same algorithm as the OTDT and OPDT channels.

The enclosed revised Technical Specification pages do not affect the conclusions of the safety evaluation and the no significant hazards evaluation performed for LAR 92-05.

Sincerely,

Warren H. Fujimoto

Subscribed and sworn to before me this 27th day of August 1993

Saundra V. Jackson, Notary Public

cc: Edgar Bailey, DHS Bobby H. Faulkenberry Ann P. Hodgdon Mary H. Miller Sheri R. Peterson CPUC Diablo Distribution

Enclosure

6213S/85K/DW0/2232

Attorneys for Pacific Gas and Electric Company Howard V. Golub Christopher J. Warner

Richard F. Locke

OFFICIAL SEAL SAUNDRA V. JACKSON NOTARY PUELIC - CALIFORNIA San Francisco County . My Commission Expires Jan. 10, 1094

## •

,

,

.

.

. .