

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Central Michigan University
 Office of Research and Graduate Studies
 Foust Hall 251
 Mt. Pleasant, Michigan 48859
 REPORT NUMBER(S) 2016-002

2. NRC/REGIONAL OFFICE

Region III
 U. S. Nuclear Regulatory Commission
 2443 Warrenton Road, Suite 210
 Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-00811

4. LICENSE NUMBER(S)

21-01432-02

5. DATE(S) OF INSPECTION

December 19, 2016

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
 (Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE	Dr. Jennifer Walton		
NRC INSPECTOR	Michael LaFranzo		12/23/16
BRANCH CHIEF	Michael Kunowski		1-4-17

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Central Michigan University Office of Research and Graduate Studies Foust Hall 251 Mt. Pleasant, Michigan 48859 REPORT NUMBER(S) 2016-002	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-00811	4. LICENSE NUMBER(S) 21-01432-02	5. DATE(S) OF INSPECTION December 19, 2016
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87104	7. INSPECTION FOCUS AREAS 03.01
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3620	2. PRIORITY 5	3. LICENSEE CONTACT Dr. Jennifer Walton - RSO	4. TELEPHONE NUMBER (989) 774-4189
--------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: NA

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

The inspection focused on the licensee's decommissioning activities and future submittal of the Final Status Survey associated with Brooks Hall and CART Building. The licensee is using a consultant, Chase Environmental Group Inc., based out of Louisville, Kentucky who is operating under reciprocity within NRC jurisdiction (Docket No. 150-00016).

While on-site, the inspector performed limited radiological surveys of areas the licensee believed were impacted by previous radiological operations and discussed with the licensee requirements under NRC regulations for the licensee to submit documentation to remove the two buildings from the license.

Observations and Findings

The inspector noted that the licensee had oversight of the contractors activities concerning remediation and radiation surveys. The inspector performed limited scope radiological surveys of rooms in Brooks Hall and CART Building; no significant radiological residual contamination was identified.

In order to release the buildings for unrestricted use and remove them from the license, the licensee shall submit a Final Status Survey in accordance with 10 CFR 30.36.