NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201		U.S. NUCLEAR REGULATO	RY COMMISSION
	ETY INSPECTION REPORT	AND COMPLIANCE INSPECTION	
1. LICENSEE/LOCATION INSPECTED: University of Connecticut 3102 Horsebarn Hill Road, Unit 4097 Storrs, Connecticut  REPORT NUMBER(S)  2017-001 & 2017-002		2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER	(S) 5. DATE(S) OF INSPECTI	ON
03010576	06-01450-47	January 24-26, 30, 20	
Regulatory Commission (NRC) rules a procedures and representative record    X	and regulations and the conditions of ls, interviews with personnel, and ob findings, no violations were identified sed.  ally described to you by the inspecto, and corrective action was or is beir	license as they relate to radiation safety and to compliant for your license. The inspection consisted of selective examples exactly servations by the inspector. The inspection findings are add.  The inspection findings are add.  The inspection findings are add.	ninations of as follows:
Non-cited violat	tion(s) were discussed involving the	following requirement(s) and corrective action(s):	
cited in accordance with		below and/or attached, were in violation of NRC requirem orm is a NOTICE OF VIOLATION, which may be subject t actions)	
corrective actions is made in accorda	e actions described by me to the Insp nce with the requirements of 10 CFF	orrective Actions  pector will be taken to correct the violations identified. Thi R 2.201 (corrective steps already taken, corrective steps we written response to NRC will be required, unless specifical	hich will be taken,
Title  LICENSEE'S REPRESENTATIVE	Printed Name	Signature	Date
NRC INSPECTOR	Dennis Lawyer	/RA/	1/30/17
BRANCH CHIEF	Blake Welling	/RA/	1/30/17
*NRC FORM 591M PART 1 (07-2012	(RI Rev. 09/12/2013)	G:\WordDocs\Current\Insp Record\R06-01450-47.201700	01.591mp1.doc
SUNSI Review Completed By:	/RA / Dennis Lawyer	X Public X	Non-Sensitive