

cc w/enclosure:

- Daniel M. Head, Esq.
- Dr. Marvin M. Mann
- Dr. William E. Martin
- Joseph F. Tubridy, Esq.
- Mr. Gustave A. Linenberger
- Mr. J. Bruce MacDonald
- Arvin E. Upton, Esq.
- Eugene B. Thomas, Jr., Esq.
- James P. McGranery, Jr., Esq.
- Ms. Suzanne Weber
- Atomic Safety and Licensing
Board Panel
- Atomic Safety and Licensing
Appeal Board
- Mr. Frank W. Karas

DISTRIBUTION:

- Formal File (2)
- Bordenick
- Massar
- Shapar
- Engelhardt
- OGC Files
 - Pink
 - Green
- REG Central.
- LPDR
- PDR
- A. Bournia - DL
- J. Norris - EP

OFFICE ▶	OGC				
SURNAME ▶	Bordenick/fmr <i>BMM</i>				
DATE ▶	Massar <i>MA</i>				
	9/6/73				

DISTRICT OF COLUMBIA

FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)


FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)

FORWARD (10)



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION I

~~870 BROAD STREET~~
~~NEWARK, NEW JERSEY 07102~~
631 Park Avenue

King of Prussia, Pennsylvania 19406

AUG 23 1973

Niagara Mohawk Power Corporation
ATTN: Mr. Thomas J. Brosnan
Vice President and
Chief Engineer
300 Erie Boulevard, West
Syracuse, New York 13202

Docket No. 50-410

Gentlemen:


This refers to the inspection conducted by Mr. William M. Hayward of this office on June 14, 1973 of activities relating to your application for an AEC Construction Permit, and to the discussions of our findings held by Mr. Hayward with Messrs. Dise and Bassett of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the Regulatory Operations Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with plant personnel, and observations by the inspector.

Within the scope of this inspection, no violations or safety items were observed.

In accordance with Section 2.790 of the AEC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the AEC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

It is our understanding that corrections and amendments to the Quality Assurance Program are being prepared, that issues of revisions and additions are scheduled to be completed and will be made available for our examinations upon completion.



AUG. 22 1973

Niagara Mohawk Power Corporation - 2 -

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

E. Morris Howard

E. Morris Howard, Chief
Facility Construction and
Engineering Support Branch

Enclosure:
RO Inspection Report
No. 50-410/73-01

