



Donald W. Gregoire
Columbia Generating Station
P.O. Box 968, PE20
Richland, WA 99352-0968
Ph. 509.377.8616 | F. 509.377.4674
dwgregoire@energy-northwest.com

February 21, 2017
GO2-17-041

10 CFR 50.54(q)

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 205551

**Subject: COLUMBIA GENERATING STATION, DOCKET NO. 50-397;
SUMMARY OF CHANGES AND ANALYSIS FOR REVISION 17 OF EPIP 13.13.2
EMERGENCY EVENT TERMINATION AND RECOVERY OPERATIONS**

Dear Sir or Madam:

Enclosed is the summary of changes and analysis for Revision 17 of Emergency Plan Implementing Procedure (EPIP) PPM 13.13.2 Emergency Event Termination and Recovery Operations issued on January 24, 2017. The changes to this EPIP have been evaluated in accordance with 10 CFR 50.54(q) and 10 CFR 72.44(f). The EPIP, as revised, continues to meet the standards of 10 CFR 50.47(b) and the requirements of 10 CFR 50 Appendix E. Enclosure 1 contains a summary of changes and evaluations performed. Each change was evaluated in accordance with the station's 10 CFR 50.54(q) evaluation process. These changes do not create a reduction in effectiveness (RIE) of the approved emergency plan.

This submittal contains no new or revised regulatory commitments. Should you have any questions or desire additional information regarding these matters, please contact Charles R Forrester at (509) 377-2290.

Executed on the 21st day of February, 2017.

Respectfully,

A handwritten signature in black ink, appearing to read "D. W. Gregoire", written over a white background.

D. W. Gregoire
Manager, Regulatory Affairs and Performance Improvement

Enclosure: Summary of Changes and Analysis

cc: NRC Region IV Administrator
NRC NRR Project Manager
NRC Sr. Resident Inspector / 988C
Director – Spent Fuel Storage & Transportation, NMSS
CD Sonoda, BPA / 1399 (email)
WA Horin – Winston & Strawn (email)