

APPENDIX A

NOTICE OF VIOLATION

Based on the results of an NRC inspection conducted on January 23-26, 1979, it appears that one of your activities was not conducted in full compliance with the conditions of your NRC Facility License No. DPR-63, as indicated below. This item has been categorized as an infraction.

Technical Specification 4.3.7.a.(2) requires that at least once per quarter operability of the four containment spray pumps shall be checked.

Contrary to the above, data from the most recent surveillance test, performed November 11, 1978, contained pump capacity values, which for two of the four pumps tested, did not meet the acceptance criteria as set forth in Surveillance Procedure NI-ST-Q6, Containment Spray and Raw Water Pumps Operability Test. The above surveillance test had been reviewed by the Operations Department and signed as acceptable.

7903290201



1950