

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7907050354 DOC. DATE: 79/06/28 NOTARIZED: NO DOCKET #
 FACILITY: 50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220
 AUTH. NAME: DUDA, E. AUTHOR AFFILIATION: Niagara Mohawk Power Corp.
 RECIP. NAME: REGION 1, Philadelphia, Office of the Director
 RECIPIENT AFFILIATION: Region 1, Philadelphia, Office of the Director

SUBJECT: LER 79-015/03L-0 on 790610: during refueling outage, time delay device in reactor protection sys would not operate in appropriate manner. Caused by bad clutch coil. Coil replaced & retested.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: INCIDENT REPORTS

NOTES: -----

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	05 BC ORB 3	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 KREGER	1	1	25 PWR SYS BR	1	1
	26 AD/SITE ANAL	1	1	27 OPERA LIC BR	1	1
	28 ACIDENT ANLYS	1	1	29 AUX SYS BR	1	1
	E JORDAN/IE	1	1	HANAUER, S.	1	1
	TMI DOC CENTER	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

JUL 6 1979

204
CCP

TOTAL NUMBER OF COPIES REQUIRED: LTTR 48 ENCL 48



Handwritten scribble or mark in the top right corner.