

September 11, 1979

Office of Inspection and Enforcement
Region I
Attention: Mr. R. T. Carlson, Chief
Reactor Construction and
Engineering Support Branch
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. Carlson:

Re: Nine Mile Point Unit 2
Docket No. 50-410


On August 2, 1979, your staff was informed of a potential deficiency at the Nine Mile Point Unit 2 site regarding the use of safety related post applied water stops. Preliminary information regarding the seismic and hydrostatic test of the union of straight lengths of post applied water stops indicated that there was leakage. Subsequent detailed evaluation of the test data concludes that the unions showed no measurable leakage.

Since the post applied water stops union did not leak, there are no safety implications. No corrective action is required.

This letter serves as a final report in accordance with Title 10, Section 50.55 (e) of the Code of Federal Regulations.

Very truly yours,

NIAGARA MOHAWK POWER CORPORATION


J. Bartlett
Executive Vice President

PEF:jk

xc: Office of Inspection and Enforcement
Washington, D.C.

7910170030

