

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8001230196 DOC. DATE: 80/01/14 NOTARIZED: NO DOCKET #
 FACIL: 50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220
 ADTH. NAME AUTHOR AFFILIATION
 DISE, D.P. Niagara Mohawk Power Corp.
 RECIP. NAME RECIPIENT AFFILIATION
 IPPOLITO, J.A. Operating Reactors Branch 3

SUBJECT: Discusses new util position re installation of voltage alarms. Safety grade alarm sys will be installed as final solution generator sets by Spring 1981. Surveillance will continue in accordance w/NRC 780807 ltr.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: General Distribution for after Issuance of Operating Lic

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	05 BC ORB #3	7				
INTERNAL:	01 REG FILE	1		02 NRC PDR	1	
	12 I&E	2		14 TA7E00	1	
	15 CORE PERF BR	1		17 ENGR BR	1	
	18 REAC SFTY BR	1		19 PLANT SYS BR	1	
	20 EEB	1		21 EFCT TRT SYS	1	
	22 BRINKMAN	1		EPB-DUR	1	
	OELD	1				
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	
	23 ACRS	16	16			

JAN 24 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 39 ENCL 0

12/1/84



THE
 UNITED STATES
 DEPARTMENT OF THE INTERIOR
 BUREAU OF LAND MANAGEMENT
 WASHINGTON, D. C. 20250

[Faint, illegible text, possibly a title or header section]

[Faint, illegible text, possibly a date or reference number]



Donald P. Dise
Vice President
Engineering

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

January 14, 1980

Director of Nuclear Reactor Regulation
Attn: Mr. Thomas A. Ippolito, Chief
Operating Reactors Branch #3
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Gentlemen:

Re: Nine Mile Point Unit 1
Docket No. 50-220
DPR-63

In our letter of December 29, 1978 we indicated that under and over voltage alarms would be installed on the reactor protection system motor-generator sets by the end of 1979 at Nine Mile Point Unit 1.

Since that time, we have re-evaluated our position. We feel that a safety grade alarm system should be installed on the motor generator sets as a final solution. This modification will be completed by the end of the Spring 1981 refueling outage. However, in the interim we will continue the surveillance as outlined in your August 7, 1978 letter.

Very truly yours,

NIAGARA MOHAWK POWER CORPORATION

D. P. Dise
Vice President - Engineering

MGM:jk

*A001
S 1/0*

8001280196

Page 1

RECEIVED
GENERAL INVESTIGATIVE DIVISION
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D. C.

MEMORANDUM FOR THE DIRECTOR
FROM THE SAC, [illegible]
SUBJECT: [illegible]

[Illegible typed text]

Very truly yours,
[Illegible Signature]

[Illegible typed text]

[Illegible typed text]

[Illegible mark]