

CENTRAL FILE

A012



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

April 3, 1980

Docket No. 50-410

Niagara Mohawk Power Corporation  
ATTN: Mr. G. K. Rhode  
Vice President  
System Project Management  
300 Erie Boulevard, West  
Syracuse, New York 13202

Gentlemen:

The enclosed IE Circular No. 80-07, "Problems with HPCI Turbine Oil System," is forwarded to you for information. No written response is required. If you desire additional information regarding this matter, please contact this office.

Sincerely,

*Robert V. Grier*  
for Boyce H. Grier  
Director

Enclosures:

1. IE Circular No. 80-07
2. List of Recently Issued IE Circulars

CONTACT: D. L. Capton  
(215-337-5254)

cc w/encls:  
Eugene B. Thomas, Jr., Esquire

*D*

8004180/80

