

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No. 80-03
Docket No. 50-410
License No. CPPR-112 Priority - Category A
Licensee: Niagara Mohawk Power Corporation
300 Erie Boulevard, West
Syracuse, New York 13202
Facility Name: Nine Mile Point Nuclear Station, Unit 2
Inspection at: Scriba, New York
Inspection conducted: April 24, 1980
Inspectors: *B. W. McGaughy* 6-9-80
A. C. Cerne, Reactor Inspector date signed
R. A. Feil 6-9-80
R. A. Feil, Reactor Inspector date signed
date signed
Approved by: *B. W. McGaughy* 6-9-80
R. W. McGaughy, Chief, Construction date signed
Projects Section, RC&ES Branch

Inspection Summary:

Inspection on April 24, 1980 (Report No. 50-410/80-03)

Areas Inspected: Routine, unannounced turnover inspection by regional based inspectors consisting of an orientation tour of the site for the newly assigned inspector. The inspection involved 6 inspector-hours onsite by two regional based inspectors.

Results: No items of noncompliance were identified.

8007180 561

DETAILS

1. Persons Contacted

Niagara Mohawk Power Corporation

S. E. Cxuba, QA Engineer
R. Dahlin, Construction Services
J. L. Dillon, QA Engineer
R. L. Patch, QA Technician

Stone & Webster Engineering Corporation (S&W)

C. E. Gay, Superintendent, Field QC
C. E. Hilton, Superintendent, Construction
J. E. Rogers, Chief Office Engineer

The inspectors conferred with other licensee and contractor personnel.

2. Facility Tour

The inspector toured the site facilities, observed work in progress and contacted various licensee and contractor personnel in the process of the turnover inspection. Areas covered included the reactor building, primary containment, turbine building, administration building, water intake structure area, the area of the ground fault and other service areas. The inspectors met with various licensee and contractor personnel to introduce the newly assigned inspector.

No items of noncompliance were identified.

3. Exit Interview

The inspectors met with licensees representatives (Paragraph 1) at the conclusion of the inspection on April 24, 1980. The inspectors explained the purpose of the inspection. The licensee acknowledged the inspectors comments.

