

July 24, 1980

Office of Inspection and Enforcement  
Region 1  
Attn: Mr. Boyce H. Grier, Director  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

Re: Nine Mile Point Unit 1  
Docket No. 50-220  
.....DPR-63.....

Your April 4, 1980 Inspection and Enforcement Bulletin 79-03A requested information regarding longitudinal weld defects in ASME SA-312 Type 304 stainless steel pipe for Nine Mile Point Unit 1.

There is no ASME SA-312 and/or A-312 fusion welded pipe in any safety related systems at Nine Mile Point Unit 1 for which the stress levels exceed 85 percent of allowable.

Very truly yours,

NIAGARA MOHAWK POWER CORPORATION



Thomas E. Lempges  
Vice President Nuclear Generation

MGM/kmb

cc: Director, Office of Inspection and Enforcement  
Division of Reactor Operations Inspection  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8008150 | 00



